YOUR ONESURVEY HOME REPORT



4e Smith Street Ayr KA7 1TD

PREPARED FOR

A Paterson

INSPECTION CARRIED OUT BY:

SELLING AGENT:





HOME REPORT GENERATED BY:



Document Index

Document	Status	Prepared By	Prepared On
Index of Documents			
Single Survey	Final	Ayr - Allied Surveyors Scotland Plc	07/03/2016
Mortgage Certificate	Final	Ayr - Allied Surveyors Scotland Plc	07/03/2016
Property Questionnaire	Final	Mr. A Paterson	08/03/2016
EPC	File Uploaded	Ayr - Allied Surveyors Scotland Plc	07/03/2016

Important Notice:

This report has been prepared for the purposes of and use of A Paterson. Should your name not be on this report then Onesurvey is unable to guarantee that this is a genuine or complete copy of the Home Report. A personalised copy of this Home Report may be obtained at www.onesurvey.org free of charge.

If you are a potential purchaser of this property you may then present your personalised copy of the report to your advisers or mortgage provider with a view to them requesting a transcription report from the appointed Chartered Surveyor.

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes



SINGLE Survey

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Surveyor Reference	AD/2589
--------------------	---------

Customer	Mr. A Paterson
----------	----------------

Customer address	4e Smith Street Ayr KA7 1TD
------------------	-----------------------------------

Date of Inspection	04/03/2016
--------------------	------------

	Mark Shanks Ayr - Allied Surveyors Scotland Plc
--	----------------------------------------------------

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\mathcal{M}}$

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 **DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 <u>Category 1</u>: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	A self-contained purpose-built second floor flat forming part of a three storey tenement of similarly styled units.
Accommodation	On one floor: Entrance hall, livingroom, kitchen, shower room and 2 bedrooms.
Gross internal floor area (m2)	60 sq m approx
Neighbourhood and location	The subjects comprise a flat situated within a predominantly private residential area. Surrounding properties are of a similar age and style of construction and the property is conveniently located for most local amenities. The property forms part of the Ayr town centre.
Age	111 yrs approx
Weather	Dry following a period of mixed weather.
Chimney stacks	Visually inspected with the aid of binoculars where required.
	The chimney stacks are of brick construction with lead apron flashing.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where required.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the


	Surveyor deems it safe and reasonable to do so.
	The roof is sloping and covered with slates. No access was gained to the roof space. However, it is assumed to be of conventional timber construction with timber sarking boards.
Rainwater fittings	Visually inspected with the aid of binoculars where required.
	Gutters and downpipes are a combination of cast iron and PVC.
Main walls	Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.
	The main external walls are of solid stone and solid brick design.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The entrance door is of timber design and windows are of replacement PVC framed double glazed design.
External decorations	None
Conservatories / porches	None
Communal areas	Circulation areas visually inspected.
	There is a common entrance and stairwell typical of properties of this type. There is no security entry system. Walls and ceilings are of lath and plaster, painted. Floors and stairs are of solid concrete design.
Garages and permanent outbuildings	None
Outside areas and boundaries	Visually inspected.
	There are communal areas to the rear which are relatively flat and comprise a combination of lawn, borders, paths and

	natio
	patio.
	Boundaries are of brick wall design.
Ceilings	Visually inspected from floor level.
	Ceilings are of plasterboard and lath and plaster design with plaster cornices.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are plastered on hard and plasterboard.
	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Floors throughout are of suspended timber design and are fully covered. A sub-floor inspection is inappropriate.
	Built-in cupboards were looked into but no stored items were moved.
kitchen fittings	Kitchen units were visually inspected excluding appliances.
	Basic kitchen units are installed with wood effect laminate door fronts and stone effect laminate countertops.
	Other internal joinery is of timber design and painted.
Chimney breasts and fireplaces	Visually inspected. No testing of the flues or fittings was carried out.
	Fireplaces and flues were an original feature of the property. However, all fireplaces have been removed and the former openings boarded over. They are no longer capable of use.
	Chimney breasts are lined with the same materials as other internal walls.
Internal decorations	Visually inspected.
	Tiling exists to the shower room and kitchen. All other areas are papered and painted.
Cellars	None

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on. There is a mains electricity supply. The installation includes a circuit breaker. Visible wiring is PVC and is connected to 13 amp sockets and switchgear. Some of the sockets are skirting mounted.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on. There is a mains gas supply.
Water, plumbing and	Visual inspection of the accessible pipework, water tanks, cylinders
bathroom fittings	and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	There is a mains water supply. Water pipework is copper and plastic.
	Sanitary fittings in the shower room are white and comprise wc, washhand basin and corner shower cubicle with mixer shower installed.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is a full gas fired central heating system incorporating a Worcester Green Star condensing combination boiler and connected to hot water radiators throughout with thermostatic radiator valves.
	The central heating boiler supplies the hot water.
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.

	Drainage is understood to be to the main public system.
Fire, smoke and burglar	Visually inspected.
alarms	No tests whatsoever were carried out to the system or appliances.
	There are smoke alarms in the property.
Any additional limits to inspection	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the Surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the Surveyor is able to give an opinion on the general condition and standard of maintenance.
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.
	The property was unfurnished. However, the floors were covered with fitted floor coverings, limiting our view of the floor surfaces and a sub-floor inspection is inappropriate.
	No access was gained to the roof space.
	The external inspection was from ground level only. The rear roof slope was not able to be viewed. Parts of the chimney stacks including apron flashing were hidden from view as were parts of parapet wall features.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

	1	Chimney pots
	2	Coping stone
	3	Chimney head
	4	Flashing
	5	Ridge ventilation
	6	Ridge board
	\bigcirc	Slates / tiles
	8	Valley guttering
	9	Dormer projection
	10	Dormer flashing
	11	Dormer cheeks
	12	Sarking
•	13	Roof felt
	14	Trusses
	15	Collar
	16	Insulation
	17	Parapet gutter
	18	Eaves guttering
	19	Rainwater downpipe
	20	Verge boards/skews
	21	Soffit boards
	22	Partiton wall
	23	Lath / plaster
	24	Chimney breast
	25	Window pointing
	26	Window sills
	27	Rendering
	28	Brickwork / pointing
	29	Bay window projection
	30	Lintels
	31	$\ensuremath{\textbf{C}}\xspace$ avity walls / wall ties
	32	Subfloor ventilator
	33	Damp proof course
	34	Base course
	35	Foundations
	36	Solum
	37	Floor joists
	38	Floorboards
	39	Water tank
	40	Hot water tank

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	3
Notes:	There is evidence of structural movement.
	While this may be contributed to be defective rainwater goods, it is not possible to confirm this is the sole cause of cracking to the external walls.
	A Structural Engineer would be able to provide further advice, including the costs for any remedial repairs required.

Dampness, rot and infestation	
Repair category:	
Notes:	Within the limitations of the inspection, there was no evidence of dampness, rot or infestation.

Chimney stacks	
Repair category:	2
Notes:	Worn brickwork, pointing and flashing was observed. Parts of the chimney stacks were hidden from view.

Roofing including roof space	

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	1
Notes:	There are a number of loose, slipped and missing slates requiring current maintenance.
	This form of roof covering requires regular maintenance and is likely to increase with time.
	Parts of the roof slopes were hidden from view.

Rainwater fittings	
Repair category:	2
Notes:	Guttering to the rear of the property is buckled and parts are choked with vegetation.
	Leaking rainwater goods are believed to have contributed to defects to the external walls.

Main walls	
Repair category:	2
Notes:	Worn brickwork, stonework and pointing was observed.
	Due to evidence of movement, structural repairs are considered necessary to the external walls. A Structural Engineer would be able to provide further advice.

Windows, external doors and joinery	
Repair category:	2

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Notes:	Misting was noted to be affecting a double glazed unit. This will require repair or replacement.
	Staining to the sealant surrounding the windows is consistent with the effects of weathering over time.
	Due to the age of the windows, increasing maintenance to seals, catches and hinges should be anticipated.

External decorations	
Repair category:	
Notes:	None

Conservatories / porches	
Repair category:	
Notes:	None

Communal areas	
Repair category:	2
Notes:	Cracked and spalled sections of render were noted to the ceilings and walls.

Garages and permanent outbuildings	
Repair category:	

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Notes:

Outside areas and boundaries	
Repair category:	
Notes:	No significant defects were identified.

Ceilings	
Repair category:	
Notes:	Old cracks were noted to some of the ceiling and cornice details.
	While these may be capable of repair during the course of redecoration, care should be taken as plasterwork, particularly of this age and design, is liable to be brittle if disturbed.

Internal walls	
Repair category:	
Notes:	Some unevenness was noted to some of the plasterwork. This has been covered over by decoration.

Floors including sub-floors	
Repair category:	
Notes:	Runs were noted to some of the flooring. This is consistent with the effects of longstanding building movement.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Movement was noted to some of the floorboards consistent with
normal wear.

Internal joinery and kitchen fittings	
Repair category:	
Notes:	There is evidence of wear and tear to the kitchen worktops.

Chimney breasts and fireplaces	
Repair category:	
Notes:	When tested with a hand held damp meter, there was no evidence of dampness to chimney breasts.

Internal decorations	
Repair category:	
Notes:	The property is well presented in good decorative order.

Cellars	
Repair category:	
Notes:	None

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Electricity	
Repair category:	
Notes:	Aspects of the installation may be dated.
	It is recommended that an electrical system is periodically checked in a 10 year cycle in order to keep up to date with frequent changes in safety legislation. Test certification should be exhibited.

Gas	
Repair category:	2
Notes:	At the time of the inspection, the gas supply had been turned off. This should be tested prior to first use to ensure its safe efficient operation.

Water, plumbing and bathroom fittings	
Repair category:	2
Notes:	At the time of the inspection, the water supply had been turned off. This should be tested prior to first use to ensure its safe and efficient operation.

Heating and hot water	
Repair category:	2
Notes:	The central heating boiler is a modern condensing type. However, it was not in operation at the time of inspection. It should be tested prior to first use by a Gas Safe registered contractor to ensure its safe and efficient operation.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Drainage	
Repair category:	
Notes:	No significant defects were identified.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information

Structural movement	3
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	1
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	2
External decorations	
Conservatories / porches	
Communal areas	2
Garages and permanent outbuildings	
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	
Electricity	1
Gas	2
Water, plumbing and bathroom fittings	2
Heating and hot water	2
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

<u>Three steps or fewer to a main entrance door of the property:</u> In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres</u>: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Second
2. Are there three steps or fewer to a main entrance door of the property?	[]YES [x]NO
3. Is there a lift to the main entrance door of the property?	[]YES [x]NO
4. Are all door openings greater than 750mm?	[]YES [x]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES []NO
6. Is there a toilet on the same level as a bedroom?	[x]YES []NO
7. Are all rooms on the same level with no internal steps or stairs?	[x]YES []NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[]YES [x]NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

Smith Street is a fully made up road which it is assumed has been adopted for maintenance by the Local Authority. It is assumed that there is free and unrestricted legal access to the property from the public road and that the existing physical boundaries coincide with the title description.

The roof and other items of the external fabric would appear to be common property with a shared maintenance liability. Common internal and external areas appear to exist with shared access rights and maintenance liabilities assumed. These details should be able to be confirmed from title.

Estimated re-instatement cost (£) for insurance purposes

170,000

One Hundred and Seventy Thousand Pounds

Valuation (£) and market comments

50,000 Fifty Thousand Pounds

Following a return in confidence to the market during 2015, properties are now generally selling well providing mortgage finance remains available and they are realistically priced.

The property is not considered to be suitable security for normal lending purposes. There is, however an established market for properties of this kind, exchanging on a "cash basis".

Report author:	Mark Shanks
Company name:	Ayr - Allied Surveyors Scotland Plc
Address:	3 Alloway Street Ayr KA7 1SP
Signed:	Electronically Signed: 73689-09401549-D9C0

Date of report: 07/03/2016

PART 2.

MORTGAGE VALUATION CERTIFICATE

Includes a market valuation of the property.





Mortgage Valuation Report

Property:	4e Smith Street Ayr KA7 1TD	Client: Mr. A F Tenure: Owne	
Date of Inspection:	04/03/2016	Reference:	AD/2589

This report has been prepared in response to your recent instructions to carry out a valuation report on the property referred to above. Please note that for most clients purchasing a property, the more detailed HOME CONDITION REPORT is recommended. This report and our inspection to which it refers have been carried out in accordance with the RICS Valuation Standards. Your attention is drawn to the additional comments elsewhere within the report, which set out the extent and limitations of the service provided. This report should be read in conjunction with the instruction acknowledgement. It is normal practice and a requirement of the RICS Valuation Standards regulations to point out that this report is for the use of the party to whom it is addressed, or their named client, or their nominated lenders, and no responsibility is accepted to any third party for the whole, or any part of its contents. Your attention is drawn to the fact that neither the whole, nor any part of this report, or any reference thereto may be included in any document, circular or statement without prior approval in writing as to the form in which it will appear

- 1	•
	.v.

LOCATION

The subjects comprise a flat situated within a predominantly private residential area. Surrounding properties are of a similar age and style of construction and the property is conveniently located for most local amenities.

The property forms part of the Ayr town centre.

2.0	DESCRIPTION			21 400:	111 vrs appro	NV.	
2.0	DESCRIPTION 2.1 Age: 111 yrs approx						
A self-contain	ed purpose-built	second floor fla	at forming part of	of a three store	y tenement of s	imilarly styled u	nits.
3.0	CONSTRUCTION						
Walls - solid brick and solid stone Roof - pitched, timber framed and slate Floors - suspended timber							
4.0	ACCOMMODATION						
On one floor: Entrance hall, livingroom, kitchen, shower room and 2 bedrooms.							
5.0	SERVICES (No tests have been applied to any of the services)						
Water:	Mains	Electricity:	Mains	Gas:	Mains	Drainage:	Mains
Central Heating: Gas fired serving panel radiators				_			
6.0	OUTBUILDINGS						
Garage:		-					

Others:		-				
7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
of the inspecti	In general terms, the property has been adequately maintained with regard to age and type. Points noted in the course of the inspection are considered to be capable of remedy in the course of routine and periodic maintenance and to be commensurate with a property of this age and type.					
		and slipped slat enance increasi		rrent maintenance. The roof co	vering is of an a	ige and type
Worn stonewo and flashing w		rk was noted to	the external wa	lls and to the chimney stacks t	ogether with wo	rn pointing
The water sup prior to first us		heating system	were not in ope	eration at the time of inspectior	n. These should	be tested
Aspects of the	e electrical syste	em may be date	d.			
8.0	ESSENTIAL property)		(as a conditior	n of any mortgage or, to preser	ve the condition	of the
confirm this is t Prior to purchas remedial repair The property is	he sole cause. se, a further ins s required. not considered	pection by a Str	ructural Enginee	ontributed to by defective gutte er is required, to provide furthe nal lending purposes. The opin	r advice and the	costs for any
8.1 Retention	recommende	d:	-			
9.0	ROADS &FO	OTPATHS				
Made up and	adopted					
10.0	BUILDINGS I (£):	NSURANCE	170,000	GROSS EXTERNAL FLOOR AREA	67	Square metres
	This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.				ion of the d. No tion and no	
11.0	GENERAL REMARKS					
Common inter	nal and externa		to exist with sha	to be common property with a ared access rights and mainter		
12.0 VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. N investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if			umed that all d obtained. No consider such contain est. It is			

	they have any concerns then they should ask for a specialist to undertake appropriate tests.						
12.1	Market Value in present condition (£):		50,000	Fifty Thousand Pounds			
12.2	2.2 Market Value on completion of essential works (£):						
12.3 Suitable security for normal mortgage purposes?		No					
12.4	Date of Valua	ation:	04/03/2016				
Signature:		Electronically	Signed: 73689-	09401549-D9C0			
Surveyor:		Mark Shanks			Date:	07/03/2016	
Ayr - Allied Surveyors Scotland Plc							
Office:	ffice: 3 Alloway Street Ayr KA7 1SP		Tel: 01292 260509 Fax: 01292 610645 email: ayr@alliedsurveyors	sscotland.com			



ENERGY **Report**

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	4e Smith Street Ayr KA7 1TD
------------------	-----------------------------------

Customer	Mr. A Paterson
----------	----------------

Customer address	4e Smith Street Ayr KA7 1TD

Prepared by Mark Shanks Ayr - Allied Surveyors Scotland Plc

Energy Performance Certificate (EPC)

Scotland

Dwellings

SECOND FLOOR REAR, 4 SMITH STREET, AYR, KA7 1TD

Dwelling type:	Top-floor flat
Date of assessment:	04 March 2016
Date of certificate:	07 March 2016
Total floor area:	60 m ²
Primary Energy Indicator:	307 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:


7816-2727-5100-0564-6906 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£2,325	See your recommendations
Over 3 years you could save*	£213	report for more information

 st based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO₂ emissions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band D (63). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D** (59). The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Internal or external wall insulation	£4,000 - £14,000	£150.00	\bigcirc
2 Low energy lighting	£25	£63.00	

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	*****	*****
	Solid brick, as built, no insulation (assumed)	★★★☆☆	★★★☆☆
Roof	Pitched, no insulation (assumed)	*****	$\bigstar \texttt{A} \texttt{A} \texttt{A} \texttt{A} \texttt{A}$
Floor	(another dwelling below)	—	—
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Boiler and radiators, mains gas	★★★ ☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	None	—	_
Hot water	From main system	★★★ ☆	★★★★ ☆
Lighting	Low energy lighting in 44% of fixed outlets	★★★ ☆☆	★★★☆☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 54 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.2 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.3 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home					
	Current energy costs	Potential energy costs	Potential future savings		
Heating	£1,851 over 3 years	£1,710 over 3 years			
Hot water	£273 over 3 years	£273 over 3 years	You could		
Lighting	£201 over 3 years	£129 over 3 years	save £213		
Total	s £2,325	£2,112	over 3 years		

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures			Typical saving	Rating after improvement		Green
Re	commended measures	Indicative cost	per year		Environment	Deal
1	Internal or external wall insulation	£4,000 - £14,000	£50	D 65	D 63	\bigcirc
2	Low energy lighting for all fixed outlets	£25	£21	D 66	D 64	

Measures which have a green deal tick \bigcirc are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick \bigcirc may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide longlasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that planning permission might be required and that building regulations apply to this work so it is best to check with your local authority whether a building warrant or planning permission will be required.

2 Low energy lighting

Replacement of traditional light bulbs with energy saving recommended ones will reduce lighting costs over the lifetime of the bulb, and they last up to 12 times longer than ordinary light bulbs. Also consider selecting low energy light fittings when redecorating; contact the Lighting Association for your nearest stockist of Domestic Energy Efficient Lighting Scheme fittings.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	10,281	(5,919)	N/A	(1,319)
Water heating (kWh per year)	1,858			

Addendum

This dwelling has stone walls and may be exposed to wind driven rain and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited. The property also requires further consideration of how to access the walls for installation of wall insulation.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. Mark Shanks
Assessor membership number:	EES/013671
Company name/trading name:	Allied Surveyors Scotland Plc
Address:	3 Alloway Street
Phone number: Email address: Related party disclosure:	Ayr KA7 1SP 01292 260509 mark.shanks@alliedsurveyorsscotland.com No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

This Certificate and Recommendations Report will be available to view online by any party with access to the report reference number (RRN) and to organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK Governments. If you are the current owner or occupier of this building and do not wish this data to be used by these organisations to contact you in relation to such initiatives, please opt out by visiting www.scottishepcregister.org.uk and your data will be restricted accordingly. Further information on this and on Energy Performance Certificates in general can be found at www.scotland.gov.uk/epc.

Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.



PART 4.

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



.

Property Questionnaire

Property address: Flot

4 • 7 •

Name of Seller(s):

Completion date of property questionnaire:

Monday 718 Marve 2016

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

•

Information to be given to prospective buyer(s)

1.	Length of ownership	
	How long have you owned the property?	Since Morenta 2004
2.	Council tax	
	Which Council Tax band is your property in? (Please circle)	
	A B C D E F G H	
3.	Parking	
	What are the arrangements for parking at your property?	
	(Please mark X in the box of all that apply)	
	• Garage	· · · · ·
	Allocated parking space	
	• Driveway	
	Shared parking	
,	On street	
	Resident permit	
	Metered parking	
	Other (please specify):	
4.	Conservation area	· · · · · · · · · · · · · · · · · · ·
	Is your property in a designated Conservation Area (that is a special architectural or historical interest, the character or ap of which it is desirable to preserve or enhance)?	

5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes No Don't Know
6.	Alterations/additions/extensions	
а.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes No Don't Know
	If you have answered yes, please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes No Don't Know
	If you have answered yes , the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes No Don't Know
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes No Don't Know
	(ii) Did this work involve any changes to the window or door openings?	Yes No Don't know
	(iii) Please describe the changes made to the windows doors, or patio doors (approximate dates when the work was completed):	with
	Please give any guarantees which you received for this work to your solicitor o	r estate agent.

•

7 .

7.	Central heating	
a.	Is there a central heating system in your property	
	(Note: a partial central heating system is one which does not hear all the main rooms of the property – the main living room, the bedoom(s), the hall and the bathroom).	Yes
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storagae heating, gas warm air).	Don't know
	If you have answered yes, please answer the three questions below:	
	i) When was your central heating system or partial central heating system installed?	Prior to Quantity
	ii) Do you have a maintenance contract for the cental heating system?	
	If you have answered yes, please give details of the company with which you have a maintenance contract:	Yes No
		Don't know
	iii) When was your maintenance agreement last renewed?	I
	(Please provide the month and the year).	
		-
8.	Energy Performance Certificate	_
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes
	NOTE: The surveyor will provide this within his inspection	
9.	Issues that may have affected your property	L
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes
	(<u>If you have answered yes</u> , is the damage the subject of any outstanding insurance	No
	claim?	Don't know
b.	Are you aware of the existence of asbestos in your property?	Yes
	· · · · · · · · · · · · · · · · · · ·	No
	<u>If you have answered yes</u> , please give details:	Don't know
L	Page 43	1

r -

Services	Connected	Supplier	
Gas or liquid petroleum gas	/	E-on (pupul	your)
Water mains or private water supply	/	Scottion Walter	
Electricity	/	Eron (Pepayo	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
Mains drainage	/	En on (Pepergo Sourceptie bone	
Telephone			
Cable TV or satellite			
Broadband			
]
<u>f you have answered yes, ple</u>	ease answer the two o		Yes
s there a septic tank system <u>f you have answered yes</u> , ple i) Do you have appropriate c	ease answer the two o		No Don't know Yes No Don't know
<u>f you have answered yes, ple</u>	onsents for the discha	rge from your septic tank?	No Don't know Yes

• •

		· · · · · · · · · · · · · · · · · · ·
1.	Responsibilities for shared or common areas	
.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:	Yes No Don't know
).	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Yes
	If you have answered yes, please give details: Only bommon report planed between the owner of the 6 flats in the block	Don't know
•	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes No Don't know
	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?	Yes
	If you have answered yes, please give details: bornon areas and as build garden close access to street	Don't know
•	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	Ves No
	If you have answered yes, please give details:	Don't know
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) <u>If you have answered yes</u> , please give details:	Yes No Don't know
2.	Charges appealated with your property	
	Charges associated with your property	
•	Is there a factor or property manager for your property? <u>If you have answered yes</u> , please provide the name and address, and give details of any deposit held and approximate charges:	Yes No Don't know

b.	Is there a common buildings insurance policy?	Yes
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges? Yes/No	No Don't know
c .	Please give details of any other charges you have to pay on a regular b common areas or repair works, for example to a residents' association, fund.	

13.	Specialist works	
а.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? <u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	Yes No Don't know
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? <u>If you have answered yes</u> , please give details:	Yes No Don't know
С.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please</u> write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	Yes No Don't know

14.	Guarantees					
a.	Are there guarantees or warranties for a	any of the follo	wing: Highl	ight in bold		
(i)	Electrical work	No	Yes	Don't know	With title deeds	Lost
(ii)	Roofing	No	Yes	Don't know	With title deeds	Lost
(111)	Central heating	No	Yes	Don't know	With title deeds	Lost
(iv)	National House Building Council (NHBC)	No	Yes	Don't know	With title deeds	Lost
(v)	Damp course	(No)	Yes	Don't know	With title deeds	Lost
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No	Yes	Don't know	With title deeds	Lost
b.	If you have answered 'yes' or 'with installations to which the guarantee(s) re		please giv	e details of	the work o	r
с.	Are there any outstanding claims under any of the guarantees listed above? Yes If you have answered yes, please give details:					\sim
15.	Boundaries					
	last 10 years?					Yes

•

16.	Notices that affect your property	
	In the past three years have you ever received a notice:	
а.	advising that the owner of a neighbouring property has made a planning application?	No
b.	that affects your property in some other way?	No
C.	that requires you to do any maintenance, repairs or improvements to your property?	No
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):

(type your name here)

7/3/10

allan Paterson (Mid barricke Property LTO)

Date: