YOUR ONESURVEY HOME REPORT



11b Baird Road Kilmarnock KA3 7RN

PREPARED FOR

Mary Paterson

INSPECTION CARRIED OUT BY:

SELLING AGENT:

Donald Ross Residential -Kilmarnock

HOME REPORT GENERATED BY:





Document Index

Document	Status	Prepared By	Prepared On
Index of Documents			
Single Survey	Final	D M Hall - Irvine	23/05/2017
Mortgage Certificate	Final	D M Hall - Irvine	23/05/2017
Property Questionnaire	Final	Mrs. Mary Paterson	23/05/2017
EPC	File Uploaded	D M Hall - Irvine	25/05/2017

Important Notice:

This report has been prepared for the purposes of and use of Mary Paterson. Should your name not be on this report then Onesurvey is unable to guarantee that this is a genuine or complete copy of the Home Report. A personalised copy of this Home Report may be obtained at www.onesurvey.org free of charge.

If you are a potential purchaser of this property you may then present your personalised copy of the report to your advisers or mortgage provider with a view to them requesting a transcription report from the appointed Chartered Surveyor.

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes



SINGLE Survey

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Surveyor Reference	IV170760
--------------------	----------

Customer	Mrs. Mary Paterson
----------	--------------------

Customer address	11b Baird Road Kilmarnock KA3 7RN
------------------	---

Date of Inspection	22/05/2017
--------------------	------------

Prepared by	Scott Baird D M Hall - Irvine
-------------	----------------------------------

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\mathcal{M}}$

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 **DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 <u>Category 1</u>: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise a purpose built first floor right hand flat within a two storey terraced flatted building which contains two flats.
Accommodation	On One Floor: Entrance Hall, Lounge, 2 Bedrooms, Kitchen, Bathroom.
Gross internal floor area (m2)	67 sq.m. or thereby.
Neighbourhood and location	 The property is situated in an established Local Authority residential area where surrounding properties are of a variety of types, some being similar. A number of surrounding properties appear privately occupied. Local amenities are available within reasonable distance in
	Kilmarnock town centre.
Age	40 years approximately.
Weather	Dull and overcast. Weather conditions over recent weeks have been mixed.
Chimney stacks	None.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where required.
	Roof spaces were visually inspected and were entered where there

	was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	ROOF
	The roof is pitched and covered with concrete tiles. The main roof structure incorporates lead lined valley gutters.
	ROOF SPACE
	I was able to inspect the roof space and gained access from a ceiling hatch within the hallway.
	The roof is built of timber trusses and boarded over with fibreboard sarking material.
	Insulation material is laid between the ceiling joists.
Rainwater fittings	Visually inspected with the aid of binoculars where required.
	Rainwater units are of PVC material.
Main walls	Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.
	The outer walls are of solid Wimpey no fines concrete construction with render external finish.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows are a mixture of UPVC double glazed replacement type and timber framed single glazed type.
	The entrance door is timber.
	There are timber fascia boards.
External decorations	Visually inspected.
	Exterior finishes are painted where appropriate.


Conservatories / porches	None.
Communal areas	Circulation areas visually inspected.
	There is a shared entrance and stairway providing access to the various flats within the building.
Garages and permanent outbuildings	None.
Outside areas and boundaries	Visually inspected.
	There are communal garden grounds surrounding the property which are generally laid in lawn and paving.
	Boundary divisions are marked by hedge.
Ceilings	Visually inspected from floor level.
	Ceilings are of plasterboard material with a decorated finish.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internal walls are of timber and plaster construction with a decorated finish.
	There are some tiled wall finishes.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring is of solid construction throughout.
Internal joinery and	Built-in cupboards were looked into but no stored items were moved.

kitchen fittings	Kitchen units were visually inspected excluding appliances.
	There are timber skirtings and door facings and internal doors are timber.
	The kitchen contains a range of floor and wall mounted storage units and worktops.
Chimney breasts and fireplaces	Visually inspected. No testing of the flues or fittings was carried out.
	There is an electric fire appliance within a timber fireplace in the lounge.
Internal decorations	Visually inspected.
	Decorative finishes are generally papered or painted.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on. Main supply. The electrical switch gear is located within the hall cupboard. Visible cabling is of PVC material and power is supplied to 13 amp sockets.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on. Main supply.
Water, plumbing and bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Main water supply. Visible pipework is of copper and PVC

	material.
	Sanitary fittings comprise "wet room" with white w.c., wash hand basin and shower cubicle.
	There is a sink unit in the kitchen.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is a wall mounted "Vokera" combination gas fired central heating boiler located within the kitchen.
	This serves water filled panelled radiators throughout the property and also provides domestic hot water.
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	Drainage is to the main sewerage system.
Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	There are smoke alarms fitted within the property.
Any additional limits to inspection	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the Surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the Surveyor is able to give an opinion on the general condition and standard of maintenance.
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a

controlled manner by specialist contractors. This can prove to be expensive.
The property was unoccupied, part furnished and floors were covered. Fitted floor coverings restricted my inspection of floor surfaces.
My internal inspection of the property including internal cupboards was in part restricted due to stored items and furnishings contained therein.
My inspection of the roof space was restricted to a head and shoulders inspection from the hatch opening due to stored items and insulation material covering the roof joists. Insulation material is not disturbed for health and safety reasons.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

1	Chimney pots
2	Coping stone
3	Chimney head
4	Flashing
5	Ridge ventilation
6	Ridge board
1	Slates / tiles
8	Valley guttering
9	Dormer projection
10	Dormer flashing
11	Dormer cheeks
12	Sarking
13	Roof felt
14	Trusses
15	Collar
16	Insulation
17	Parapet gutter
18	Eaves guttering
19	Rainwater downpipe
20	Verge boards/skews
21	Soffit boards
22	Partiton wall
23	Lath / plaster
24	Chimney breast
25	Window pointing
26	Window sills
27	Rendering
28	Brickwork / pointing
29	Bay window projection
30	Lintels
31	Cavity walls / wall ties
32	Subfloor ventilator
33	Damp proof course
34	Base course
35	Foundations
36	Solum
37	Floor joists
38	Floorboards
39	Water tank
40	Hot water tank

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	
Notes:	There is evidence of previous movement in the property but within the limitations of my inspection I found no evidence to suggest that the movement appears serious and there are no obvious signs of recent movement having occurred.

Dampness, rot and infestation	
Repair category:	1
Notes:	No reportable defects identified.

Chimney stacks	
Repair category:	
Notes:	None

Roofing including roof space	
Repair category:	
Notes:	No reportable defects identified.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Concrete tiles are typically guaranteed for 30 years but have a reasonable life expectancy around 50/60 years according to the BRE. Life expectancy will often depend on weathering and damage from the prevailing weather. A roofing contractor will be able to advise on life expectancy and repair/replacement costs.
There are loose sarking boards within the roof void area.

Rainwater fittings	3
Repair category:	
Notes:	No reportable defects identified.

Main walls	
Repair category:	
Notes:	The render finish of external walls displays evidence of surface cracking in places.

Windows, external doors and joinery	
Repair category:	
Notes:	Timber framed single glazed window units are weathered and mastic sealant is deteriorating.

External decorations	
Repair category:	1

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Notes:	Exterior decorative finishes are weathered.
--------	---

Conservatories / porches	
Repair category:	
Notes:	None

Communal areas	
Repair category:	
Notes:	There are cracked/damaged plasterwork finishes within the common stairwell area.

Garages and permanent outbuildings	
Repair category:	
Notes:	None

Outside areas and boundaries	
Repair category:	
Notes:	Garden grounds are generally overgrown.

Ceilings

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	1
Notes:	No reportable defects identified.
	Artexing to ceilings of this age may contain asbestos material. If any works within these areas are to be undertaken it is advisable to seek Specialist advice prior to work commencing.

Internal walls	
Repair category:	
Notes:	No reportable defects identified.

Floors including sub-floors	
Repair category:	
Notes:	No reportable defects identified.

Internal joinery and kitchen fittings	
Repair category:	
Notes:	There is localised damage and deterioration to internal joinery finishes and kitchen units are of older origin and display signs of general wear. An incoming occupier may wish to upgrade to their own personal taste.

Chimney breasts and fireplaces	
--------------------------------	--

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	1
Notes:	No reportable defects identified.

Internal decorations	
Repair category:	
Notes:	No reportable defects identified although decoration is of an older origin. An incoming occupier may wish to upgrade to their own personal taste.

Cellars	
Repair category:	
Notes:	None.

Electricity	
Repair category:	
Notes:	It is recommended that all electrical installation be checked every ten years to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC registered Contractor.

Gas	
Repair category:	

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Notes:	No reportable defects identified.
--------	-----------------------------------

Water, plumbing and bathroom fittings	
Repair category:	
Notes:	No reportable defects identified.

Heating and hot water	
Repair category:	
Notes:	No reportable defects identified.
	It is considered good practice that a central heating system be serviced annually to ensure that it operates efficiently and safely.

Drainage	
Repair category:	
Notes:	No reportable defects identified.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	
Communal areas	1
Garages and permanent outbuildings	
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

<u>Three steps or fewer to a main entrance door of the property:</u> In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	First
2. Are there three steps or fewer to a main entrance door of the property?	[]YES [x]NO
3. Is there a lift to the main entrance door of the property?	[]YES [x]NO
4. Are all door openings greater than 750mm?	[]YES [x]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES []NO
6. Is there a toilet on the same level as a bedroom?	[x]YES []NO
7. Are all rooms on the same level with no internal steps or stairs?	[x]YES []NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES []NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is assumed that the share of common repair work to the building fabric is apportioned equitably to the various occupiers and this can be legally confirmed by inspection of the Title Deeds.

Estimated re-instatement cost (£) for insurance purposes

115,000

One Hundred & Fifteen Thousand Pounds

Valuation (£) and market comments

45,000

Forty Five Thousand Pounds.

Market conditions remain steady at the present time.

Report author:	Scott Baird
Company name:	D M Hall - Irvine
Address:	45 Bank Street Irvine KA12 0LL
Signed:	Electronically Signed: 96143-3A495367-43EC
Date of report:	23/05/2017

PART 2.

MORTGAGE VALUATION CERTIFICATE

Includes a market valuation of the property.



HOME REPORT							
		Mort	gage Valu	uation Re	port		
Property:	11b Baird Roa Kilmarnock KA3 7RN	ıd	Client: Mrs. M Tenure: Absol	ary Paterson ute Ownership			
Date of Inspection:	22/05/2017		Reference:	IV170760			
This report has been prepared in response to your recent instructions to carry out a valuation report on the property referred to above. Please note that for most clients purchasing a property, the more detailed HOME CONDITION REPORT is recommended. This report and our inspection to which it refers have been carried out in accordance with the RICS Valuation Standards. Your attention is drawn to the additional comments elsewhere within the report, which set out the extent and limitations of the service provided. This report should be read in conjunction with the instruction acknowledgement. It is normal practice and a requirement of the RICS Valuation Standards regulations to point out that this report is for the use of the party to whom it is addressed, or their named client, or their nominated lenders, and no responsibility is accepted to any third party for the whole, or any part of its contents. Your attention is drawn to the fact that neither the whole, nor any part of this report, or any reference thereto may be included in any document, circular or statement without prior approval in writing as to the form in which it will appear							
1.0 LOCATION							
The property is situated in an established Local Authority residential area where surrounding properties are of a variety of types, some being similar. A number of surrounding properties appear privately occupied. Local amenities are available within reasonable distance in Kilmarnock town centre.							
2.0	DESCRIPTIO	N		2.1 Age:	40 years appr	oximately.	
The subjects comprise a purpose built first floor right hand flat within a two storey terraced flatted building which contains two flats.							
3.0 CONSTRUCTION							
Walls - Concrete							
Roof - Tiled							
4.0 ACCOMMODATION							
4.0	ACCOMMOD						
4.0 On One Floor:							
On One Floor:			Bathroom.				
On One Floor:	Lounge, 2 Bed			any of the se	rvices)		

Central Heati	ng:	Gas				
6.0	OUTBUILDINGS					
Garage:		None				
Others:		0				
7.0	7.0 GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
When inspected	ed the property	was unoccupied	d, part furnished	and floors were covered.		
need of a degr repair or upgra mortgage lend Evidence of pr	ree of decoratio ading. No obvio ling purposes w revious moveme	n/modernisatior us serious defe- vere identified. ent was noted ir	n. There is wear cts which would n the property, b	ensurate with age and style of and tear to some items requir have an adverse impact upon out within the limitations of our hat there were obvious signs o	ing routine main value or suitab inspection, we f	ntenance ility for ound no
				an adverse effect on future sal		lent naving
8.0	ESSENTIAL REPAIR WORK (as a condition of any mortgage or, to preserve the condition of the property)					
None apparent						
8.1 Retention	8.1 Retention recommended:					
9.0	ROADS &FO	OTPATHS				
Made up.					-	
10.0	BUILDINGS I (£):	NSURANCE	115,000	GROSS EXTERNAL FLOOR AREA	76	Square metres
This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.						
11.0 GENERAL REMARKS						
It is assumed that the share of common repair work to the building fabric is apportioned equitably to the various occupiers and this can be legally confirmed by inspection of the Title Deeds.						
12.0 VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.						
12.1	Market Value condition (£)		45,000	Forty Five Thousand Pounds	6	

12.2	Market Value completion o works (£):	-				
12.3	Suitable secu normal morto purposes?	•	r Yes			
12.4	Date of Valua	ation:	on: 22/05/2017			
Signature:		Electronically Signed: 96143-3A495367-43EC				
Surveyor:		Scott Baird			Date:	23/05/2017
D M Hall - Irvine						
Office:	fice: 45 Bank Street Irvine KA12 0LL		Tel: 01294 311070 Fax: 01294 311077 email: lynette.henderson@dmhall.co.uk			



ENERGY **Report**

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	11b Baird Road Kilmarnock KA3 7RN
------------------	---

Customer Mrs. Mary Paterson

Prepared by Scott Baird D M Hall - Irvine
--

Energy Performance Certificate (EPC)

Scotland

Dwellings

11B BAIRD ROAD, NEW FARM LOCH, KILMARNOCK, KA3 7RN

Dwelling type:	Top-floor flat
Date of assessment:	22 May 2017
Date of certificate:	24 May 2017
Total floor area:	67 m ²
Primary Energy Indicator:	250 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:

5613-4225-3200-0042-5926 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

You can use this document to:

B

Not environmentally friendly - higher CO₂ emissions

D

(81-91)

(69-80)

(55-68)

(39-54


(21-38)

(1-20)

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£2,106	See your recommendations	
Over 3 years you could save*	£702	report for more information	

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (68)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (67)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

80

67

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Cavity wall insulation	£500 - £1,500	£396.00	\bigcirc
2 Low energy lighting	£40	£120.00	
3 Condensing boiler	£2,200 - £3,000	£108.00	\bigcirc

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

F

G

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

11B BAIRD ROAD, NEW FARM LOCH, KILMARNOCK, KA3 7RN 24 May 2017 RRN: 5613-4225-3200-0042-5926

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, no insulation (assumed)	★★☆☆☆	★★☆☆☆
Roof	Pitched, 200 mm loft insulation	★★★★☆	★★★★☆
Floor	(another dwelling below)	—	
Windows	Partial double glazing	★★☆☆☆	★★☆☆☆
Main heating	Boiler and radiators, mains gas	★★★ ☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	None	—	
Hot water	From main system	★★★★☆	★★★☆
Lighting	No low energy lighting	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 44 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.9 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.1 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home				
	Current energy costs	Potential energy costs	Potential future savings	
Heating	£1,500 over 3 years	£969 over 3 years		
Hot water	£321 over 3 years	£291 over 3 years	You could	
Lighting	£285 over 3 years	£144 over 3 years	save £702	
Totals	£2,106	£1,404	over 3 years	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving per year	Rating after improvement		Green
				Energy	Environment	Deal
1	Cavity wall insulation	£500 - £1,500	£132	C 74	C 75	
2	Low energy lighting for all fixed outlets	£40	£40	C 76	C 76	
3	Replace boiler with new condensing boiler	£2,200 - £3,000	£36	C 77	C 78	
4	Replace single glazed windows with low-E double glazed windows	£3,300 - £6,500	£26	C 78	C 80	

Measures which have a green deal tick of are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick of may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- External insulation with cavity wall insulation
- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the Building Standards Division's section of the Scottish Government website (www.scotland.gov.uk/Topics/Built-Environment/Building/Building-

standards/publications/pubguide/cavitywallinsul) or the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Low energy lighting

Replacement of traditional light bulbs with energy saving recommended ones will reduce lighting costs over the lifetime of the bulb, and they last up to 12 times longer than ordinary light bulbs. Also consider selecting low energy light fittings when redecorating; contact the Lighting Association for your nearest stockist of Domestic Energy Efficient Lighting Scheme fittings.

3 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a qualified heating engineer.

4 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation		
Space heating (kWh per year)	7,429	N/A	(2,572)	N/A		
Water heating (kWh per year)	1,957					

Addendum

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name: Address:

Phone number: Email address: Related party disclosure: Mr. Greg Fisher EES/017520 D M Hall Chartered Surveyors LLP 17 Corstorphine Road Edinburgh EH12 6DD 01292286974 greg.fisher@dmhall.co.uk No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.



PART 4.

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Address:

II B BAIRD RD KILMARNOCK KA37RN

Completion date of Property Questionnaire:

19.5.17

,

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1	Length of ownership			
	How long have you owned the property?	23 y	RS	
2	Council Tax			
	Which Council tax band is your property in?	A.		
3	Parking (tick all applicable)			
	 Garage Allocated Parking Space Driveway Shared Parking On Street Resident Permit Metered Parking 			
	Other (Please specify)			
4	Conservation area			
<u> </u>			Yes	
	Is your property in a designated Conservation area (that is an area of special architectural or historical interest,		No	~
	the character or appearance of which it is desirable to		Unknown	
	preserve or enhance)?			

÷

ŝ

5	Listed buildings		<u>,</u>
		Yes	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special	No	~
	architectural or historical interest)?	Unknown	
6	Alterations/additions/extensions		
a (i)	During your time in the property, have you carried out any structural alterations, additions or extensions (for example,	Yes	
	provision of an extra bath/shower room, toilet or bedroom)?	No	V
	If you have answered Yes, please describe below the changes which you have made:	Unknown	
(ii)			
(")	Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes	
		No	
		Unknown	
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes	~
		No	
	If you have answered Yes, please answer the 3 questions below:	Unknown	
(i)	Were the replacements the same shape and type as the ones you replaced?	Yes	1
		No	
		Unknown	1
(11)	Did this work involve any changes to the window or door openings?	Yes	
		No	-
		Unknown	
(iii)	Please describe the changes made to the windows, doors, or patio doors (with approximate dates when the work was completed):		
	Please give any guarantees which you received for this work to your solicitor or estate agent.		

,

,

7	Central heating	-	
a	Is there a central heating system in your property?	Yes	
- I		No	
	(Note: a partial central heating system is one which does not heat		
	all the main rooms of the property – the main living room, the	Partial	
	bedroom/s, the hall and the bathroom)	Unknown	
	If you have answered Yes or Partial – what kind of central heating is there?		
	(Examples: gas-fired, solid fuel, electric storage heating, gas, warm air).	GAS	
	If you have answered Yes, please answer the 3 questions below:		
(1)	When was your central heating system or partial central heating system	stem installed?)
U			
(ii)	Do you have a maintenance contract for the central heating	Yes	
	system?	No	
	If you place also details of the company with which you have a	Unknown	<u> </u>
	If yes, please give details of the company with which you have a maintenance contract:		
	HYDRO ELECTRIC .		
(111)	When was your maintenance agreement last renewed? (please prov	/ide the month	and
(iii)	year)		
	MARCH 2017		
8	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old? (PLEASE NOTE: Please tick 'YES' as the surveyor will complete this at the time of inspection)	Yes	~
6	Tecues that may have affected your property		
9	Issues that may have affected your property Has there been any storm, flood, fire or other structural damage	Yes	1
а	to your property while you have owned it?	No	~
		Unknown	
			<u></u>
		Yes	<u> </u>
1	If you have answered Yes, is the damage the subject of any		
	outstanding insurance claim?	No	
		Ver	
b	Are you aware of the existence of asbestos in your property?	Yes No	
	If you have answered Yes, please give details:	Unknown	+
	a you nute unothered i coy piedoe gite decuitor		<u></u>
i	1	1	

•

÷

Services					
Please tick which services are connected to your property and give details of the supplier					
vices	Connected	Supplier			
or liquid petroleum gas			H y 1980	ELECTI	RIC
			4		
ricity			HYDRO	ELECT	21
s drainage			1		
phone		B. T.			
e TV or satellite					
dband					
Is there a septic tank sys	tem at your p	roperty?	· · · · · · · · · · · · · · · · · · ·	Yes	
				No	-
				Unknown	1
If you have answered Yes	s, please answ	er the 2 auestions	below:		
Do you have appropriate				Yes	
tank?				No	~
				Unknown	
Do you have a maintenar	nce contract fo	r your septic tank	?	Yes	
				No	~
If you have answered Yes which you have a mainte	s, please give nance contract	detalls of the com t:	pany with		
	Please tick which services vices or liquid petroleum gas er mains or private water by tricity s drainage phone e TV or satellite dband Is there a septic tank sys <u>If you have answered Yes</u> Do you have a maintenar If you have answered Yes	Please tick which services are connected vices Connected or liquid petroleum gas er mains or private water ily tricity as drainage phone e TV or satellite dband Is there a septic tank system at your propriate consents for t tank? Do you have answered Yes, please answered Yes, please answered Yes, please give	Please tick which services are connected to your property vices Connected Supplier or liquid petroleum gas Image Image er mains or private water Image Image tricity Image Image phone B Image e TV or satellite Image Image dband Is there a septic tank system at your property? If you have answered Yes, please answer the 2 questions Do you have a maintenance contract for your septic tank Image Image	Please tick which services are connected to your property and give details of the company with Vices Connected Supplier or liquid petroleum gas If you have answered Yes, please give details of the company with	Please tick which services are connected to your property and give details of the supplice vices Connected Supplier or liquid petroleum gas Image: The provide the supplice The provide the supplice er mains or private water Image: The provide the supplice The provide the supplice is drainage Image: The provide the supplice The provide the supplice phone B.T. Image: The provide the supplice of the supplice B.T. Image: The provide the supplice of the supplice Image: The provide the supplice The providet the supplice of the supplice Image: The providet the supplice The providet the supplice is drainage Image: The providet the providet the supplice The providet the providet the supplice of the providet the provi

11	Responsibilities for shared or common areas		
a	Are you aware of any responsibility to contribute to the cost of	Yes	4
	anything used jointly, such as the repair of a shared drive,	No	
	private road, boundary, or garden area?	Unknown	
	If you have answered Yes, please give details:		
b	Is there a responsibility to contribute to repair and maintenance	Yes	~
	of the roof, common stairwell or other common areas?	No	
	. J	Unknown	+
	If you have answered yes, please give details:	N/A	1
с	Has there been any major repair or replacement to any part of	Yes	-
	the roof during the time you have owned the property?	No	1
		Unknown	
d	Do you have the right to walk over any of your neighbours'	Yes	~
-	property – for example to put out your rubbish bin or maintain	No	
	your boundaries?	Unknown	<u> </u>
	If you have answered Yes, please give details:		
		Maa	· T ·
e	As far as you are aware, do any of your neighbours have the	Yes	+
	right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	Unknown	
	If you have answered Yes, please give details:		
	As far as you are aware, is there a public right of way across any	Yes	
f	part of your property? (public right of way is a way over which	No	+
	the public has a right to pass, whether or not the land is privately	Unknown	
	owned.)		
	If you have answered Yes, please give details:		
12	Charges accounted with your property		
12	Charges associated with your property Is there a factor or property manager for your property?	Yes	
а	12 mere a lacroi or higherry manager for your higherry:	No	- ⁻
	If you have answered Yes, please provide the name and address, and give details of any deposit held and approximate charges:	Unknown	

ł

, r *****

			
b	Is there a common buildings insurance policy?	Yes	
		No	~
		Unknown	
	If you have answered Yes, is the cost of the insurance included in		
	your monthly/annual factor's charges?	Yes	
		No	~
		Unknown	
c	Please give details of any other charges you have to pay on a regu upkeep of common areas or repair works, for example to a residen maintenance or stair fund.	lar basis for the ts' association, (or
13	Specialist works		
а	As far as you are aware, has treatment of dry rot, wet rot, damp	Yes	
	or any other specialist work ever been carried out to your	No	1
	property?	Unknown	
Ь	If you have answered Yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property: As far as you are aware, has any preventative work for dry rot, wet rot or damp ever been carried out to your property? If you have answered Yes, please give details:	Yes No Unknown	7
с	If you have answered Yes to 13(a) or 13(b), do you have any	Yes	
	guarantees relating to this work?		
	-	No	
	If you have answered Yes, these guarantees will be needed by	Unknown	
	the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself, <u>please</u> <u>write below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:		
ł			t

14	Gu	arantees					
а	Are there any guarantees or warranties for any of the following?						
			No	Yes	Don't know	With title deeds	Lost
i)		Electrical Work	e'				
ii)		Roofing	/				
ili)		Central Heating	~				
iv)		National House Building Council (NHBC)	1				
v)		Damp course	/				
vi)	ł	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	/				
b		you have answered 'Yes' or 'with title deed tallations to which the guarantee(s) relate		_			
	Are	e there any outstanding claims under any	of the	guara	antees	Yes	
•		ed above?		-		No	-
						Unknown	
		you have answered Yes, please give detail	5.				
15		undaries					
	So	far as you are aware, has any boundary	of you	ir prop	erty beer	Yes	
	m	oved in the last 10 years?				No Unknown	
	If	you have answered Yes, please give detai	ls?				
						1	
1							

16	Notices that affect your property		
In t	he past 3 years have you ever received notice:		
		Yes	
а	Advising that the owner of a neighbouring property has made a	No	
	planning application?	Unknown	
		Yes	
b	That affects your property in some other way?	No	2
		Unknown	
		Yes	
С	That requires you to do any maintenance, repairs or	No	
	improvements to your property?	Unknown	
agen	u have answered Yes to any of a-c above, please give the notices to it, including any notices which arrive at any time before the date of e our property.	your solicitor or ntry of the purc	estate haser

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s): Many Patenson

Date:

· · · ·

19 5.17

9