




SIDE ELEVATION



REAR ELEVATION

- Existing brick lintels to external openings to be retained and repared as required.
- Existing timber lintels (external and internal to be removed as required and replaced with new oak lintels. Sizes to match existing where replaced and subject to Structural Engineers recommendations.
- Repair mortar pointing to external walls where required. Mortar to match existing.
- 4. Repair mortar pointing internally where
- 5. Timber framed double glazed windows.
- Timber door frames.
- Existing slate roof coverings to be retained/repaired as required.
- Timber fascia's/ bargeboards to be replaced with new to match existing.
- Where indicated existing stone walls to be taken down and rebuilt to match existing. Pointing to match existing.