



## **Description**

A detached two storey commercial building of single portal frame construction with brick work elevations underneath a pitched insulated roof. The unit benefits from a securable yard area to the right flank and rear of the building. At ground floor level the building provides a split between open workspace, office and reception areas. The first floor is in substantially open plan work/storage space format.

The roller shutter loading door opens up to the first floor level enabling fork lift loading.

- Good natural daylight
- · 3m to underside of first floor slab
- Separate male and female toilet facilities
- Rear yard
- Substantially refurbished building
- Three phase power and gas



Mercury House is situated on the western side of Lea Road, just past the junction with Gordon Road. Lea Road junctions with the A121 Station Road a short distance to the north, from where there is good access out to junctions 25 and 26 of the M25 via Waltham Cross and Waltham Abbey. Waltham Cross railway station, with links into London Liverpool Street, is within less than 1 mile away.

	Sq ft	Sq m
Ground Floor	6,004	558
First Floor Office	6,004	558
Rear Building	1,574	146
Total	13,662	1,262



**VAT** Not Applicable

**EPC** E102

Rateable Value £81,000

Price/ Rent Upon Application

## **Contacts**

Chris Wade 07816 505718

chris.wade@strettons.co.uk

Harry Robins 07866 075 899 harry.robins@strettons.co.uk

Further information | View on Website

Strettons and their clients give notice that: 1. They are not authorised to make or give any representations or warranties in relation to the property either here or elsewhere, either on their own behalf or on behalf of their client or otherwise. They assume no responsibility for any statement that may be made in these particulars. These particulars do not form part of any offer or contract and must not be relied upon as statements or, representations of fact. 2. Any areas, measurements or distances are approximate. The text, photographs and plans are for guidance only and are not necessarily comprehensive. It should not be assumed that the property has all necessary planning, building regulation or other consents and the Agents have not tested any services, equipment or facilities. Purchasers must satisfy themselves by inspection or otherwise.