

Landlord Gas Safety Record

Cert. No. 327

YOUR LOCAL GAS COMPANY

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / I	Installer			Job Addr	ress						Custo	omer / l	Landlord							
Engineer	JASON SAN	JASON SANGER											9							
Company			ICES (WALES) Ltd.	Address	8	820						oany	Davies Homes							
Address	MYDAM LO	DGE		-,			Carmarthen Road						ess	8						
	19 Mydam Lane					F	Fforestfach							Borough road						
Gorseinon						9	Swansea							Gorseinon						
	SWANSEA	Post Code	9 9	SA58HS							Swansea									
Post Code												Post (Post Code SA4 6RP							
Tel No.						Tel. No 01792448979								79						
Gas Safe Reg	Gas Safe Reg 227395																			
ID Card No. 4489433																				
Appliance D	etails						Inspec	ction Details												
Location			Make	Mod	el	Flue Typ	e Landlord's Appliance Inspected		Operating Pressure	Heat Input (kW/h)			ow Combustio			Visual condition		Appliance	Appliance safe	
							Appliance		(mbar)		Readin Ratio CO		Reading tio CO CO	correct operation	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
											ppm	n	ppm 9	6		satisfactory				
1 Airing Cupl		Combi Boiler	Alpha	Eco 2		RS	Yes	Yes	18	NA	.0001 97		NA N		Yes	Yes	Pass	Yes	Yes	
2 Kitche	n	Hob	Gas	Stain	less	FL	Yes	Visual	NA	NA	NA NA	A NA N	A NA N	A Yes	Yes	Yes	Pass	Yes	Yes	
3																				
5																				
6																				
	1.6.								Laholc a	and Warning No	ntico Issued		A.I. /	1		C I	A.L. /	7		
Defects / Identified								Labels and Warning Notice Issued					CO Alarm(s)				Smoke Alarm(s)			
2					NA NA					-	CO Alarm(s) fitted Yes				Smoke Alarm(s) fitted Yes					
3								NA				CO Aldiff(3) fitted			Smoke Alaim(s) nitted Tes					
4												CO A	CO Alarm(s) tested			Smoke Alarm(s) tested				
5												Satisfacto		Pass		isfactory		Pass		
6	6																			
Emergency Co	ntrol Access	ible Yes Gas	Tightness Satisfactory Ye	s	Comr	nents	5													
Gas Installation Pipework Visual Inspection Satisfactory Yes																				
Number of Appliances Tested 1 Equipotential Bonding Yes																				
NEXT INSPECTION DUE ON OR BEFORE 18-Sep-2020																				
Signatures Issued by:	Signed				Received S	Signed	4		-			Da	ate	18-S	ep-2019					
		(45))	l	oy:			AS												
Print Name		JASON SANGER	R	I	Print Name		J SANO	GER												