

Landlord Gas Safety Record

Cert. No. 1623

PLATINUM PROPERTY SERVICES (WALES)Ltd.
Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Coı	mpany / I	nstaller	r		Job Address						Custor	Customer / Landlord									
Engineer		JASON SANGER				Name							Name								
Company Address Post Code		PLATINUM PROPERTY SERVICES (WALES)Ltd. MYDAM LODGE 19 Mydam Lane				Address	1	.2					Compa	ny	Davies Hor	mes					
							Voylart Close					Addres	S	8							
								Dunvant							Borough road						
		Gorseinon						Swansea							Gorseinon						
		SWANSEA				Post Code		SA27TZ								Swansea					
						Tel. No	Ů.	3,2,12				Post Code Tel. No	5.13.1355								
		SA4 4YA											01792448979								
Tel No.		01792897455																			
Gas Safe Reg		227333																			
טו	Card No.	5296621																			
Apı	oliance D	etails						Inspec	tion Details												
	Location		Appliance Type	Make	Mode	el	Flue Type				Heat Input (kW/h)			Combustion			Visual condition of flue and		Appliance	Appliance safe	
								Appliance		(mbar)		Reading Ratio CO	CO2 % Ratio	Reading CO CO	correct operation	Provision satisfactory	termination satisfactory	Performance test	Serviced	to use	
												ppm		ppm %	5		-				
1	Utility	'	Combi Boiler	Ideal	Independer	nt + C30	RS	Yes	Yes	19	NA	.0011 99	9.13 NA	NA N	A Yes	Yes	Yes	Pass	Yes	Yes	
2																					
3																					
4																					
5																					
6																					
De	fects / Ide	dentified								Labels and Warning Notice Issued				CO Alarm(s)				Smoke Alarm(s)			
1									NA			CO Alarm(s) fitted Yes				Smoke Alarm(s) fitted Yes					
2													CO Ala	arm(s) fi	ttea	Yes	Smoke	Alarm(s) fit	tea	Yes	
4												CO Ala	arm(s) te	actad		Smoke	Alarm(s) te	ctad			
5														atisfacto		Pass		tisfactory	steu	Pass	
6																		-			
Emergency Control Accessible Yes Gas Tightness Satisfactory Yes Comments																					
Gas Installation Pipework Visual Inspection Satisfactory Yes																					
		•		,																	
	Equipotent	ial Bondir	ng Yes																		
NEXT INSPECTION DUE ON OR 16-Nov-2023 BEFORE																					
Sia	natures																				
Issued by:		Signed			Received Signed by:							Date	e	11-	Nov-2022						
Pri	nt Name		JASON SANGER		F	Print Name		J SANO	GER												